



Recommended Spare Parts List

Mentor Radio, LLC. Recommends that where failure of a radio would present serious operational problems a complete spare radio be kept on hand for each 4 radios or any part thereof.

The following recommended spare parts are for 1 to 4 radios; for 5-8 radios the quantities should be doubled.

This revision is for M15's made after November 1998 that contain pc boards marked "1101392S" on the top of the board. For boards whose part numbers end in L, M, N, P and R an earlier revision of this page applies.

Part Number	Description	Quantity
1101444	Transistor, 2N4427	1
1101445	Transistor, MRF237	1
1101661	Transistor, MRF1946A	1
1101108	Transistor, BF908	1
1100653	Transistor, MPS5172	1
1101346	Transistor, 2N5772	1
2100432	Transistor, 2N4126	1
1101447	Transistor, 2N6107	1
1100048	Diode, 1N295	1
1101198	Diode, MA4P1250	1
1100838	IC, LM3900	1
1101111-08	IC, MC78L08	1
1101134	IC, MC14016B	1
1101660	IC, LMC662	1
1101662	FET, J175	1
1101443	IC, LM383	1
2100456	IC, CA3028A	1
2100029-103	Potentiometer/Switch, 10K	1
1101263-104	Potentiometer, 100K	1
1101457	Fuse, 2AG 4amp	5